

# Oil Field Environmental Incident Summary

**Incident:** 20150502142649      **Date/Time of Notice:** 05/02/2015 14:26

**Responsible Party:** CONOCOPHILLIPS COMPANY

**Well Operator:** CONOCOPHILLIPS COMPANY

**Well Name:** DICKINSON-LODGEPOLE UNIT 79

**Field Name:** DICKINSON

**Well File #:** 13554

**Date Incident:** 5/2/2015      **Time Incident:** 07:38

**Facility ID Number:**

**County:** STARK

**Twp:** 140

**Rng:** 96

**Sec:** 31

**Qtr:** NW NE

**Location Description:** This is a pipeline leak that occurred on the line between the Dickinson lodgepole unit 74 and the Dickinson lodgepole unit 79. The leak occurred in the right of way between the two wells in the area west of 113th avenue SW and south of 35 Street SW.

**Submitted By:** Lewis Schoenberger

**Received By:**

**Contact Person:** Lewis Schoenberger  
PO BOX 358  
BORGER, TX 79008-0358

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.5 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	5	Barrels				
Other						

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 7/21/2016      **Clean Up Concluded:** 5/20/2016

**Risk Evaluation:**

None

**Areal Extent:**

approximately 100 feet by 30 feet.

**Potential Environmental Impacts:**

Surface soils are likely to be impacted.

**Action Taken or Planned:**

Most of the impacted soil is on the pipeline right of way. The production well has been shut in and the pipeline has been taken out of service. The area of the leak will be excavated with a hydrovac system. The pipeline will be repaired. The produced water impacted soil in the right of way will be excavated and removed for appropriate disposal. If the property owner agrees, the produced water impacted soil adjacent to the right of way will be excavated and sent for appropriate disposal.

**Wastes Disposal Location:****Agencies Involved:****Updates**

---

**Date:** 5/4/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of location along a pipeline right of way. Followup is necessary.

---

**Date:** 5/11/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived at the site at 16:46 p.m. The weather was clear, 57°F, with the wind from the northwest at 10-15 mph. The break occurred near the same area in the alfalfa field as in March of 2014. Currently, a new road is being built on south side of the pipeline right of way. The pipeline break area has been dug up, along with an area of the field going west in the field. More followup needed.  
46.89785; - 102.83595

---

**Date:** 5/28/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Requested clearance samples and documentation.

---

**Date:** 5/29/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received sample results and maps.

---

**Date:** 6/5/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived at the site at 9:27 a.m. The weather was sunny, 59°F, with the wind from the southeast 5-10 mph. The excavation area is still open and part of it fenced off. More follow-up needed.

---

**Date:** 6/8/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Response on the sample results; will do more assessment of site.

---

**Date:** 6/8/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Sent response for samples received and a copy of draft guidelines.

---

**Date:** 6/10/2015    **Status:** Awaiting Documentation

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Requested a copy of work plan.

---

**Date:** 7/24/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

The company is planning to conduct investigation activities at this site the week of August 24, 2015.

---

**Date:** 7/27/2015    **Status:** Awaiting Documentation

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

An assessment plan will be sent to the NDDoH.

---

**Date:** 7/28/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Talked to the consultant. She will be at the site in August to do more assessment work.